

SDS PREVENTATIVE MAINTENANCE KIT


There is a new PM (Preventative Maintenance) kit for the SDS unit.

Background

A change was made to the standard UV unit installed in the SDS product in early 2018. The Aquafine UV unit for the SDS is no longer available from the manufacturer. The replacement UV unit is supplied by Viqua. The Viqua unit uses a different lamp part number from the Aquafine unit. The UV lamp is included in the PM kit.

This Tech Note identifies the active PM kit part numbers associated with the model of UV unit installed. Both PM kit part numbers remain active and are available.

SDS with UV Model	PM Kit Part No.
Aquafine	W3T578233
Viqua	W3T578760



For ordering, verify the model of the UV unit installed on the SDS. Refer to the table above for the PM kit part number.

Please be sure to contact Technical Support at 888-595-0666 if you have any questions or require further assistance.