

DISCONTINUED ELEMENT INFORMATION (Medical Devices)

The following elements, have been discontinued by the manufacturer. We have optional replacements that will require purchase of a different style element and/or a complete ROMA (Reverse Osmosis Membrane Assembly). This generally includes the housing, element, end caps, and fittings. In some cases, additional fittings and tubing will be required (i.e., Series 700 RO units).

CAUTION

If switching from a CA (Cellulose Acetate) material to the more common TFC (Thin Film Composite) material, please note that chlorine removal must be performed before the RO element or damage to the element(s) will occur.

| Discontinued Part Number | Replacement Part Number | Description of change |
|--|--|--|
| ME40179A | ME14647 | Tape wrapped element with extended brine seal to fit in full size housings. |
| ME40599A ***As of the time of this Technote creation, a small stock is still available but once gone no more will be available. | 3024436 | Complete ROMA and required parts. Required on first converting from old style housing. For element replacement after initial installation, element ME40599 must be purchased. |
| ME40091A and ME40510A | 3019663 ***Additional fittings may be required depending on RO, consult Technical Support. | Converts from CA element material (ME40091A only) and housing(s) to current TFC element and housing(s). For element replacement after initial installation, element OS1206719 must be purchased. |

DISCONTINUED ELEMENT INFORMATION (Non Medical Devices)

The following elements have been discontinued by the manufacture with no replacement. Therefore these are discontinued with no direct replacement available. Please contact your local Mar Cor Service or Sales representative for assistance in converting to a potential compatible element or to a newer device.

| Discontinued Part Numbers | | | |
|---------------------------|--------------------|------------|--------------------|
| 475-02-001 | 112 HR(CA) element | 475-02-004 | 112 HR(CA) element |
| 475-02-051 | 192 HR element | 475-02-054 | 192 HR(PA) element |
| 475-04-054 | 411 HF(PA) element | 475-04-154 | 416 HR element |
| 475-04-151 | 416 HR(PA) element | 475-04-001 | 704 HR(CA) element |